National Transportation Safety Board NTSB ID: LAX96LA254 Aircraft Registration Number: N260DG FACTUAL REPORT Occurrence Date: 06/29/1996 Most Critical Injury: Minor Occurrence Type: Accident Investigated By: NTSB ETYBO Location/Time Nearest City/Place State Zip Code Local Time Time Zone PDT CA 93060 1630 SANTA PAULA Distance From Landing Facility: Direction From Airport: 40 Airport Proximity: Off Airport/Airstrip Aircraft Information Summary Aircraft Manufacturer Model/Series Type of Aircraft **GRAY BERKUT** Airplane Sightseeing Flight: No Air Medical Transport Flight: No

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On June 29, 1996, at 1630 hours Pacific daylight time, an experimental Gray Berkut, N260DG, collided with a tree and an automobile during an emergency landing after an in-flight loss of power while on final approach to the Santa Paula Airport, Santa Paula, California. The airplane was being operated by the pilot/owner as a flight under 14 CFR Part 91 when the accident occurred. The airplane was destroyed. The airline transport rated pilot and the four occupants of the vehicle struck by the aircraft all received minor injuries. The flight originated from Camarillo, California, at 1600. Visual meteorological conditions prevailed at the time.

The pilot/owner/builder had completed the airplane's first test flight after the Federal Aviation Administration (FAA) issued an experimental airworthiness certificate for amateur built aircraft. The pilot was in the process of positioning the airplane to the Santa Paula Airport. He reported the engine lost power on final approach. The pilot attempted to restart the engine without success. He then elected to attempt an off-airport landing on the westbound lanes of a freeway. The pilot indicated he was too low and landed on the center median. The airplane struck an automobile that moved from the traffic lanes to the median to avoid the airplane.

The airplane's engine was examined on October 29, 1996, at Lynn's Aircraft Engines, El Monte, California. During the examination, no evidence was found of a mechanical failure, nor were any malfunctions discovered that explained a loss of engine power.

According to aircraft maintenance records, the fuel pump was overhauled on December 7, 1995, by Aero Accessories Inc., Gibsonville, North Carolina, a Federal Aviation Administration (FAA) Certified Repair Station. The repair station issued FAA Form 813.0-3, "Airworthiness Approval Tag" at the time of the overhaul. In addition, the pilot reported that the airplane had accrued a total time of .7 hours. No evidence was found that indicated the fuel pump was operated in any other engine since the overhaul.

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: LAX96LA254

Occurrence Date: 06/29/1996

FACIUAL REPOR	1	Occu	inence D	Jaie. (16/29/1996								
AVIATION Occurre				ype: A	Accident								
Landing Facility/Approach Inf	ormation												
Airport Name			Airport ID: A		Airport Eleva	tion	Run	way Used	Runway Lengt		th	Runway Wid	
SANTA PAULA			SZP	SZP 25		MSL	22	22		2500		60	
Runway Surface Type: Asphalt							_						
Runway Surface Condition: Dry													
Type Instrument Approach: NONE													
VFR Approach/Landing: Straight-in	า												
Aircraft Information													
Aircraft Manufacturer				odel/Se						Serial Number			
GRAY			BI	ERKL	JT ————					043			
Airworthiness Certificate(s): Experi	imental (Special)												
Landing Gear Type: Retractable -	Tricycle												
Homebuilt Aircraft? Yes	Number of Seats: 2	Cer	Certified Max Gross Wt.				2000 LBS Nur		Numbe	ımber of Engines: 1			
Engine Type: Reciprocating									Model/Series: IO-540-G4B5			Rated Power: 260 HP	
- Aircraft Inspection Information													
Type of Last Inspection			Date of Last Inspection			Time Si	ime Since Last Inspection				Airframe Total Time		
Annual				06/1996						1 Hours			
- Emergency Locator Transmitter (E	ELT) Information												
ELT Installed? No	ELT Operate	ed?		ELT	Aided i	n Locating Ac	cident S	Site?					
Owner/Operator Information													
Registered Aircraft Owner	Street Address 611 MONTE VISTA												
DANIEL GRAY				City								•	Zip Code
				SANTA PAULA									93060
Operator of Aircraft				Street Address Same as Reg'd Aircraft Owner									
Same as Reg'd Aircraft Owner	City							State	9	Zip Code			
Operator Does Business As:							O	perator Desig	nator Co	ode:			
- Type of U.S. Certificate(s) Held: N	lone												
Air Carrier Operating Certificate(s):													
Operating Certificate:					Operator C	Certific	cate:						
Regulation Flight Conducted Under	: Part 91: Genera	al Aviat	tion		•								
Type of Flight Operation Conducted													
]	FACT	UAL RE	EPOR'	T - AVIATI	ON							Page 2

National Transportation Safety Board

FACTUAL REPORT

AVIATION

NTSB ID: LAX96LA254

Occurrence Date: 06/29/1996

AVIATION	Occurrence Type: Accident										
First Pilot Information											
Name	City			Sta	te [Date of Birth	Age				
On File	On File			On	File	On File	41				
Sex: M Seat Occupied:	Prir	ncipal Profes	n Pilot	t Certificate Number: On File							
Certificate(s): Airline Transport; Flight Instructor; Commercial											
Airplane Rating(s): Multi-engine Land; Single-engine Sea											
Rotorcraft/Glider/LTA: Helicopter											
Instrument Rating(s): Airpla	ane										
Instructor Rating(s): Airplane Multi-engine; Airplane Single-engine; Helicopter; Instrument Airplane											
Type Rating/Endorsement for	r Accident/In	cident Aircra	ft? No			Current Bie	nnial Flight l	Reviev	v?		
Medical Cert.: Class 1	ivers/lim.	Date of Last Medical Exam: 06/1996									
	•						•				
- Flight Time Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Mult-Engine	Night	In Actual	strument Simulated	I		Glider	Lighter Than Air
Total Time	21000	2	5000	15000	4000	50	00		100	0	
Pilot In Command(PIC)	19000	2	5000	13000	4000	50	00		100	0	
Instructor	5000		4000	500				_	50	0	
Last 90 Days	200	1	10	190			1	5			
Last 30 Days	70	1	5	65				5			
Seatbelt Used? Yes	Last 24 Hours 1 1 1 1 eatbelt Used? Yes Shoulder Harness Used? Yes Toxicology Performed? No Secon							cond Pilot? No	<u> </u>		
Seatbelt Used? Yes Shoulder Harness Used? Yes Toxicology Performed? No Second Pilot? No									,		
Flight Plan/Itinerary											
Type of Flight Plan Filed: No	ne										
Departure Point						State Airport Ide		entifier Departur		ure Time	Time Zone
CAMARILLO	CA	A CMA			1600		PDT				
Destination	State	e A	Airport Identifier								
Same as Accident/Incident Location							ZP				
Type of Clearance: None					-						
Type of Airspace: Class C	3										
Weather Information											
Source of Briefing: No record of briefing											
Method of Briefing:											
			FACTUAL	REPORT -	- AVIATIO	N					Page 3

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: LAX96LA254

Occurrence Date: 06/29/1996

Occurrence Type: Accident

Weather Information WOF ID **Observation Time** Time Zone WOF Elevation WOF Distance From Accident Site Direction From Accident Site PDT CMA 1646 75 Ft. MSL 192 Deg. Mag. 0 Ft. AGL Sky/Lowest Cloud Condition: Clear Condition of Light: Day Lowest Ceiling: None 0 Ft. AGL Visibility: 40 Altimeter: 29.00 SM "Hg Temperature: 29 °C Dew Point: 10 °C Wind Direction: 210 Density Altitude: Ft. Weather Condtions at Accident Site: Visual Conditions Wind Speed: 9 Gusts: Visibility (RVR): 0 Ft. Visibility (RVV) 0 SM Intensity of Precipitation: Unknown Restrictions to Visibility: None None Type of Precipitation: Accident Information Aircraft Damage: Destroyed Aircraft Fire: None Aircraft Explosion None Classification: U.S. Registered/U.S. Soil - Injury Summary Matrix Fatal Serious Minor None TOTAL First Pilot 1 Second Pilot Student Pilot Flight Instructor Check Pilot Flight Engineer Cabin Attendants Other Crew Passengers - TOTAL ABOARD -1 1 Other Ground 0 0 4 4 - GRAND TOTAL -0 0 5 5

National Transportation Safety Board

FACTUAL REPORT AVIATION

NTSB ID: LAX96LA254

Occurrence Date: 06/29/1996

Occurrence Type: Accident

Administrative I	Informatior
------------------	-------------

Investigator-In-Charge (IIC)

THOMAS H. WILCOX

Additional Persons Participating in This Accident/Incident Investigation:

GORDEN CAMPBELL WP-VNY-FSDO VAN NUYS, CA 91406

DANIEL P GRAY 611 MONTE VISTA SANTA PAULA, CA 93060